

GMC P1815: TFP MANUAL VALVE POSITION SWITCH CIRCUIT MALFUNCTION

OVERVIEW

Severity	:	High
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$200-\$350
Can I Still Drive?	:	

What Does The GMC P1815 Code Mean?

No VSS DTCs [P0502](#) or [P0503](#). The transmission OSS is less than 250 RPM. The engine speed is in transition from 0 RPM to greater than 625 RPM.

Reference Sources

[Technical Service Bulletin PIP5094 for P1815](#) - General Motors