CIRCUIT MALFUNCTION		
		OVERVIEW
Severity	:	High
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$200-\$350
Can I Still Drive?	:	Yes (Short-term only)

## What Are The Symptoms Of The GMC P1816 Code?

## What Are The Potential Causes Of The GMC P1816 Code?

- Faulty Automatic Transmission Fluid Pressure (TFP) Manual Valve Position Switch
- TFP Valve Position Switch harness is open or shorted
- TFP Valve Position Switch circuit poor electrical connection

## **Reference Sources**

Technical Service Bulletin PIP5094 for P1816 - General Motors

