

What Does The GMC P1875 Code Mean?

Engine started, vehicle driven to a speed over 7 mph for 5 seconds, gear range is D4, Fuel Cutoff not active, TP angle from 17-50%.

What Are The Potential Causes Of The GMC P1875 Code?

- 4WD low switch signal circuit is open, shorted to ground or B+
- 4WD low switch is damaged or has failed
- PCM has failed

Reference Sources

[Technical Service Bulletin PIP5094 for P1875](#) - General Motors