

HONDA B1007: MICU LOST COMMUNICATION WITH COMBINATION SWITCH CONTROL UNIT (HLSW MESSAGE)

OVERVIEW

Severity :  Medium

DIY Difficulty Level :  Intermediate

Repair Cost : **\$75-\$200**

Can I Still Drive? : **Yes** (Short-term only)

What Does The Honda B1007 Code Mean?

Poor communication between the MICU and the Combination Switch Control Unit. Inoperative or intermittent Headlamp Switch.

What Are The Potential Causes Of The Honda B1007 Code?

- Loose or poor connections between the MICU and the Combination Switch Control Unit.
- Blown fuse in the main under-hood fuse box
- Blown fuse in the under-dash fuse/relay box
- Faulty MICU
- Faulty Headlamp Switch (Combination Switch Control Unit).

Reference Sources

[Technical Service Bulletin 08-078 for B1007](#) - Americann Honda Motor Co., Inc, 2005-2009 Odyssey