

HONDA B1230: SHORT IN THE SUNLIGHT SENSOR CIRCUIT

OVERVIEW

| | | |
|----------------------|---|------------------------------------|
| Severity | : | <div><div>Medium</div></div> |
| DIY Difficulty Level | : | <div><div>Intermediate</div></div> |
| Repair Cost | : | \$100-\$350 |
| Can I Still Drive? | : | Yes (Short-term only) |

What Does The Honda B1230 Code Mean?

Poor communication between the Sunlight Sensor and the Climate Control Unit – (“Short”) condition.

What Are The Potential Causes Of The Honda B1230 Code?

- Perform the HVAC self-diagnostic function with the HDS
- “Short” in the wires between the Climate Control Unit and the Sunlight Sensor
- Faulty Sunlight Sensor
- Faulty Climate Control Unit

Reference Sources

[Body Electrical Repair Information for B1230](#) - American Honda Motor, page 89.