

What Does The Honda P1361 Code Mean?

Engine running, and the PCM detected an unexpected or intermittent interruption of the Top Dead Center (TDC) sensor signal.

What Are The Potential Causes Of The Honda P1361 Code?

- TDC signal circuit is open or shorted to ground
- TDC signal circuit is shorted to VREF or system power
- TDC pickup assembly or its pulse rotor is damaged
- PCM has failed

Reference Sources

Technical Service Bulletins 01-083 for P1361 - Honda Motor Co., Ltd., 2001 Civic EX

