

What Does The Hyundai B1476 Code Mean?

Enable Conditions Ignition "ON" Threshold Value Rs < $2k\Omega$ Diagnostic Time Qualification More than 4 sec De-Qualification More than 8 sec

What Are The Potential Causes Of The Hyundai B1476 Code?

- Short to power in CAB harness.
- Poor connection of connected part.
- Poor connection between shorting bar and release pin.
- Faulty CAB.
- Faulty SRSCM.

Reference Sources

SRSCM (SRS Control Module) General Information for B1476 - Hyundai Genesis Coupe, pages 213-216.

