HYUNDAI B2579: RIGHT REAR TAIL MARKER LAMP SHORT TO GROUND

OVERVIEW

Severity : Medium

DIY Difficulty Level : Intermediate

Repair Cost : \$50-\$150

Can I Still Drive? : Yes (Short-term only)

What Are The Potential Causes Of The Hyundai B2579 Code?

- Short in power circuit
- Light bulb failure

Reference Sources

Hyundai B2579, DTCDECODE.

