

HYUNDAI B2581: RIGHT REAR TAIL MARKER LAMP OPEN

OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$50-\$150
Can I Still Drive?	:	Yes (Short-term only)

What Are The Potential Causes Of The Hyundai B2581 Code?

- Open in power circuit
- Light bulb failure

Reference Sources

[Hyundai B2581](#), DTCDECODE.