

Hyundai P1765: TCS-ITM CAN Communication Line

OVERVIEW

Severity

:

High

DIY Difficulty Level

:

Advanced

Repair Cost

:

\$900-\$1300

Can I Still Drive?

:

No

What Are The Potential Causes Of The Hyundai P1765 Code?

- ECM,TCCU connector looseness and poor terminal to wire connection
- CAN HIGH/LOW circuit open/short
- Faulty ECM
- Faulty TCCU

Reference Sources

[Transaxle / Transmission Repair Information for P1765](#) - Page 89-92.