

Infiniti C1101: ABS RR Wheel Speed Sensor 1

OVERVIEW

Severity

:

High

DIY Difficulty Level

:

Intermediate

Repair Cost

:

\$100-\$300

Can I Still Drive?

:

No

What Does The Infiniti C1101 Code Mean?

Circuit of rear RH wheel sensor is open. Or when the sensor power voltage is outside the standard.

What Are The Potential Causes Of The Infiniti C1101 Code?

- Harness or connector
- Wheel sensor
- ABS actuator and electric unit
- (control unit)

Reference Sources

[Technical Service Bulletin for C1101](#) - Nissan North America, Inc.; 2007-2013 Infiniti vehicles equipped with ABS/VDC