

## INFINITI C1109: BATTERY VOLTAGE ABNORMAL TO ABS ACTUATOR

### OVERVIEW

Severity	:	<div><div>High</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$75-\$250
Can I Still Drive?	:	<b>Yes</b> (Short-term only)

### What Does The Infiniti C1109 Code Mean?

When the ABS actuator and electric unit (control unit) power supply voltage is lower or higher than normal.

### What Are The Potential Causes Of The Infiniti C1109 Code?

- Harness or connector
- ABS actuator and electric unit (control unit)
- Fuse
- Ignition power supply system
- Battery

### Reference Sources

[ProDemand Automotive Repair Information](#) - 2014 Infiniti QX60 Base