

Infiniti C1704: LF Low Pressure Signal

OVERVIEW

Severity

:

Medium

DIY Difficulty Level

:

Intermediate

Repair Cost

:

\$200-\$310

Can I Still Drive?

:

No

What Does The Infiniti C1704 Code Mean?

TPMS light on. Low pressure in tire.

What Are The Potential Causes Of The Infiniti C1704 Code?

- Tire pressure
- Ambient cold condition
- Tire
- Valve stem and/or TPMS sensor
- Transmitter
- BCM

Reference Sources

[Technical Service Bulletin WT20-001 for C1704](#) - 2014-2020 Q50 and 2017-2020 Q60