INFINITI C1729: VEHICLE SPEED SIGNAL IS IN ERROF		
		OVERVIEW
Severity	:	Medium
DIY Difficulty Level	:	Intermediate
	·	
Repair Cost	:	\$75-\$200

What Does The Infiniti C1729 Code Mean?

The vehicle speed signal is not being detected by the BCM.

What Are The Potential Causes Of The Infiniti C1729 Code?

- CAN communication system
- Combination meter

Reference Sources

Road Wheels & Tires Repair Information for C1729 - 2009 Pathfinder, page 19.

