

INFINITI P1440: EVAP CANISTER SYSTEM SMALL LEAK (0.040") DETECTED:

OVERVIEW

Severity	:	Medium
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$200-\$600
Can I Still Drive?	:	Yes (Short-term only)

What Does The Infiniti P1440 Code Mean?

Engine started, vehicle driven at cruise speed at light engine load, and the PCM detected a small leak present in the EVAP system with the Purge and Canister Control Vent solenoids "on" in the Leak test.

What Are The Potential Causes Of The Infiniti P1440 Code?

- Fuel filler cap loose, damaged or incorrect application
- EVAP canister vent valve is damaged or contaminated
- EVAP system leaks (in canister or related vapor lines)
- EVAP control system vapor pressure sensor line is blocked
- MAP/BARO switch sole

Reference Sources

[Technical Service Bulletin EC10-038 for P1440](#) - 1998-later Infiniti vehicles with EVAP service port