INFINITI P1441: VACUUM CUT VALVE BYPASS VALVE CIRCUIT MALFUNCTION: OVERVIEW DIY Difficulty Level : Intermediate

Repair Cost : \$100-\$400

Can I Still Drive? : Yes

What Does The Infiniti P1441 Code Mean?

Engine started, vehicle driven at cruise speed at light engine load, and the PCM detected an unexpected voltage on the EVAP Vacuum Cut Valve Bypass circuit during the CCM test.

What Are The Potential Causes Of The Infiniti P1441 Code?

- EVAP vacuum cut valve bypass valve circuit is open
- EVAP vacuum cut valve bypass valve circuit shorted to ground
- EVAP vacuum cut valve bypass valve is damaged or has failed
- PCM has failed

Reference Sources

Infiniti QX4 (R50) Manual for P1441

