

JEEP P1051: INTAKE VALVE CONTROL SOLENOID 1 CIRCUIT LOW

OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div>Advanced</div>
Repair Cost	:	\$60-\$410
Can I Still Drive?	:	Yes (Short-term only)

What Does The Jeep P1051 Code Mean?

There are four Variable Valve Lift (VVL) Solenoids that control the operation of the Intake Rocker Arms for all six cylinders.

What Are The Potential Causes Of The Jeep P1051 Code?

- VVL solenoid 1/1 control circuit shorted to ground
- VVL solenoid 1/1 control circuit shorted to the VVL solenoid 1/1 ground circuit
- VVL solenoid 1/1
- Powertrain control module (PCM)

Reference Sources

[Jeep P1051](#), DTCDECODE.