

JEEP P1052: INTAKE VALVE CONTROL SOLENOID 1 CIRCUIT HIGH

OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div>Advanced</div>
Repair Cost	:	\$60-\$410
Can I Still Drive?	:	Yes

What Does The Jeep P1052 Code Mean?

There are four Variable Valve Lift (VVL) Solenoids that control the operation of the Intake Rocker Arms for all six cylinders.

What Are The Potential Causes Of The Jeep P1052 Code?

- VVL solenoid 1/1 control circuit shorted to voltage
- Powertrain control module (PCM)

Reference Sources

[Jeep P1052](#), DTCDECODE.