

JEEP P1053: INTAKE VALVE CONTROL SOLENOID 2 CIRCUIT/OPEN

OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div>Advanced</div>
Repair Cost	:	\$60-\$410
Can I Still Drive?	:	Yes (Short-term only)

What Does The Jeep P1053 Code Mean?

There are four Variable Valve Lift (VVL) Solenoids that control the operation of the Intake Rocker Arms for all six cylinders.

What Are The Potential Causes Of The Jeep P1053 Code?

- VVL solenoid 1/2 control circuit open/high resistance
- VVL solenoid 1/2 ground circuit open/high resistance
- VVL solenoid 1/2
- Powertrain control module (PCM)

Reference Sources

[Jeep P1053](#), DTCDECODE.