

## JEEP P1793: TORQUE MANAGEMENT REQUEST CIRCUIT MALFUNCTION

### OVERVIEW

<b>Severity</b>	:	High
<b>DIY Difficulty Level</b>	:	Advanced
<b>Repair Cost</b>	:	\$45-\$850
<b>Can I Still Drive?</b>	:	No

### What Does The Jeep P1793 Code Mean?

Key on and the TCM did not detect any signals on the Torque Management Request circuit.

### What Are The Potential Causes Of The Jeep P1793 Code?

- Extremely low battery (system) voltage
- Torque management request circuit is open, shorted to ground or shorted to system power (i. e. , the TRD circuit has failed) or the TCM has failed.

### Reference Sources

[Jeep P1793](#), DTCDECODE.