

LEXUS P1405: TURBO PRESSURE SENSOR CIRCUIT MALFUNCTION

OVERVIEW

Severity	:	High
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$200-\$350
Can I Still Drive?	:	Yes (Short-term only)

What Does The Lexus P1405 Code Mean?

Engine started, engine running, and the PCM detected an unexpected voltage condition on the Turbo Boost Pressure sensor circuit during the CCM test.

What Are The Potential Causes Of The Lexus P1405 Code?

- Boost Pressure sensor signal circuit open or shorted to ground
- Boost Pressure sensor power or ground circuit is open
- Boost Pressure sensor is damaged or has failed
- PCM has failed

Reference Sources

[Lexus P1405](#), DTCDECODE.