

Lexus P1604: PCM Internal Dual-Port Ram Read/Write Integrity Failure

OVERVIEW

Severity

:

High

DIY Difficulty Level

:

Advanced

Repair Cost

:

\$500-\$1000

Can I Still Drive?

:

No

What Are The Potential Causes Of The Lexus P1604 Code?

- Fused ignition switch output is missing (off-start-run circuit)
- PCM is damaged or it has an internal failure

Reference Sources

[Lexus P1604](#), DTCDECODE.