

Lexus P1740: TCM Internal Malfunction

OVERVIEW

Severity

:

High

DIY Difficulty Level

:

Advanced

Repair Cost

:

\$500-\$900

Can I Still Drive?

:

No

What Are The Potential Causes Of The Lexus P1740 Code?

- ATF fluid is burnt, contaminated or contains excessive debris
- A/T cooler flow restriction or problems in the oil pump shaft
- Internal transmission problem (O/D clutch seals or valve body)
- Overdrive clutch or TCC clutch is damaged or has failed
- Transmission valve body is leaking, damaged or has failed

Reference Sources

[Lexus P1740](#), DTCDECODE.