

LEXUS P1793: TCM TRD LINK COMMUNICATION ERROR

OVERVIEW

Severity	:		High
DIY Difficulty Level	:		Intermediate
Repair Cost	:	\$50-\$300	
Can I Still Drive?	:	No	

What Are The Potential Causes Of The Lexus P1793 Code?

- Torque Management Request (TMR) sense circuit is open or is shorted to ground or to voltage
- PCM or TCM has failed
- Intermittent wiring and connector problems

Reference Sources

[Lexus P1793](#), DTCDECODE.