MALFUNCTION			
		OVERVIEW	
Severity	:		High
DIY Difficulty Level	:	Adva	nced
Repair Cost	:	\$150-\$800	

## What Are The Potential Causes Of The Lexus P1794 Code?

- Extremely low battery (system) voltage
- TCM "reset" function has just been performed

## **Reference Sources**

Lexus P1794, DTCDECODE.