

MAZDA C1117: RPM INPUT CIRCUIT FAILURE

OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$75-\$200
Can I Still Drive?	:	Yes (Short-term only)

What Are The Potential Causes Of The Mazda C1117 Code?

- Malfunction of engine control system
- Malfunction of related wiring harness

Reference Sources

[Mazda C1117](#), DTCDECODE.