MAZDA P1444: EVAP PURGE FLOW SENSOR CIRCUIT LOW INPUT OVERVIEW Severity : Medium DIY Difficulty Level : Intermediate Repair Cost : \$150-\$300 Can I Still Drive? : Yes (Short-term only)

What Does The Mazda P1444 Code Mean?

Key on or engine running and the PCM detected the EVAP Purge Flow (PF) sensor signal was less than 0.20v during the CCM test.

What Are The Potential Causes Of The Mazda P1444 Code?

- Purge flow sensor signal circuit is shorted to ground
- Purge flow sensor power circuit is open
- Purge flow sensor is damaged or has failed
- PCM has failed

Reference Sources

Mazda P1444, DTCDECODE.

