

MAZDA U2510: COMMUNICATION ERROR BETWEEN THE INSTRUMENT CLUSTER AND THE PCM (NO RESPONSE)

OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$75-\$200
Can I Still Drive?	:	Yes (Short-term only)

What Does The Mazda U2510 Code Mean?

Communication error between the instrument cluster and the PCM (no response)

What Are The Potential Causes Of The Mazda U2510 Code?

- Malfunction in the wiring harness (CAN line) between the instrument cluster and the PCM
- PCM malfunction
- Instrument cluster malfunction

Reference Sources

[Mazda U2510](#), DTCDECODE.