

MERCEDES-BENZ P1031: LEFT AND RIGHT O2 SENSORS, BEFORE TWC, MISPOSITIONED

OVERVIEW

Severity	:	Medium
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$50-\$400
Can I Still Drive?	:	Yes (Short-term only)

What Are The Potential Causes Of The Mercedes-Benz P1031 Code?

- Test plug connections.
- Reposition or replace sensors as needed.

Reference Sources

[Mercedes-Benz P1031](#), DTCDECODE.