

MERCEDES-BENZ P1179: OIL SENSOR SIGNAL RE OIL TEMPERATURE IMPLAUSIBLE

OVERVIEW

Severity	:	High
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$100-\$1100
Can I Still Drive?	:	No

What Are The Potential Causes Of The Mercedes-Benz P1179 Code?

- Wrong actual value or oil sensor re oil level, temperature and quality.
- Deficient power supply of oil sensor.

Reference Sources

[Mercedes-Benz P1179](#), DTCDECODE.