

MERCEDES-BENZ P1358: EXHAUST VALVE (CYL. 5) NOT OPERATED AT CYLINDER CUTOFF

OVERVIEW

Severity	:	High
DIY Difficulty Level	:	Advanced
Repair Cost	:	\$300-\$700
Can I Still Drive?	:	No

What Are The Potential Causes Of The Mercedes-Benz P1358 Code?

- The rocker arm coupling at the exhaust valve of cylinder 5 does not lock although the CSO is switched off.
- Determine the faulty rocker arm by testing smooth engine running.
- Replace faulty rocker arm.

Reference Sources

[Mercedes-Benz P1358](#), DTCDECODE.