MERCEDES-BENZ P1360: EXHAUST VALVE (CYL. 3) NOT OPERATED AT CYLINDER CUTOFF			
Sovority			High
Severity	:		High
DIY Difficulty Level	:		Advanced
Repair Cost	:	\$300-\$700	

## What Are The Potential Causes Of The Mercedes-Benz P1360 Code?

- The rocker arm coupling at the exhaust valve of cylinder 3 does not lock although the CSO is switched off.
- Determine the faulty rocker arm by testing smooth engine running.
- Replace faulty rocker arm.

## **Reference Sources**

Mercedes-Benz P1360, DTCDECODE.

