OPERATED AT CYLINDER CUTOFF			
		OVERVIEW	
Severity	:		High
DIY Difficulty Level	:		Advanced
Repair Cost	:	\$300-\$700	

What Are The Potential Causes Of The Mercedes-Benz P1361 Code?

- The rocker arm coupling at the exhaust valve of cylinder 8 does not lock although the CSO is switched off
- Determine the faulty rocker arm by testing smooth engine running
- Replace faulty rocker arm

Reference Sources

Mercedes-Benz P1361, DTCDECODE.

