

MERCEDES-BENZ P1361: EXHAUST VALVE (CYL. 8) NOT OPERATED AT CYLINDER CUTOFF

OVERVIEW

Severity	:	High
DIY Difficulty Level	:	Advanced
Repair Cost	:	\$300-\$700
Can I Still Drive?	:	No

What Are The Potential Causes Of The Mercedes-Benz P1361 Code?

- The rocker arm coupling at the exhaust valve of cylinder 8 does not lock although the CSO is switched off
- Determine the faulty rocker arm by testing smooth engine running
- Replace faulty rocker arm

Reference Sources

[Mercedes-Benz P1361](#), DTCDECODE.