OPERATED AT CYLINDER CUTOFF			
		OVERVIEW	
Severity	:	F	ligh
DIY Difficulty Level	:	Advan	ced
Repair Cost	:	\$300-\$700	
Repair Cost Can I Still Drive?	:	\$300-\$700 No	

What Are The Potential Causes Of The Mercedes-Benz P1380 Code?

- The rocker arm coupling of an inlet valve does not lock although the CSO is switched off.
- Replace faulty rocker arm(s).
- NOTE; The fault P1380 can only be detected by analysing smooth engine running in the upper engine load and speed range.

Reference Sources

Mercedes-Benz P1380, DTCDECODE.

