

MERCEDES-BENZ P1386: KNOCK SENSOR CONTROL FROM ECM

OVERVIEW

Severity	:	High
DIY Difficulty Level	:	Advanced
Repair Cost	:	\$100-\$2000
Can I Still Drive?	:	Yes (Short-term only)

What Are The Potential Causes Of The Mercedes-Benz P1386 Code?

- Increased knock tendency due to bad fuel, carbon in combustion chamber or mechanical damage
- Engine control module

Reference Sources

[Mercedes-Benz P1386](#), DTCDECODE.