MERCEDES-BENZ P1386: KNOCK SENSOR CONTROL FROM ECM		
	•	OVERVIEW
Severity	:	High
DIY Difficulty Level	:	Advanced
Repair Cost	:	\$100-\$2000
Can I Still Drive?	:	Yes (Short-term only)

## What Are The Potential Causes Of The Mercedes-Benz P1386 Code?

- Increased knock tendency due to bad fuel, carbon in combustion chamber or mechanical damage
- Engine control module

## **Reference Sources**

Mercedes-Benz P1386, DTCDECODE.

