

MERCEDES-BENZ P1491: A/C REFRIGERANT SYSTEM PRESSURE TOO HIGH

OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$200-\$500
Can I Still Drive?	:	Yes

What Are The Potential Causes Of The Mercedes-Benz P1491 Code?

- Check A/C refrigerant levels.
- Check for frost on A/C lines, indicating blockage.
- Receiver-drier.

Reference Sources

[Mercedes-Benz P1491](#), DTCDECODE.