

NISSAN C1105: ABS RR WHEEL SPEED SENSOR 2

OVERVIEW

Severity	:	<div><div>High</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$100-\$300
Can I Still Drive?	:	No

What Does The Nissan C1105 Code Mean?

This code sets:

- When the circuit in the rear RH wheel sensor is short-circuited or power voltage is unusual.

Or

- When the distance between the wheel sensor and sensor rotor is too large and the sensor pulse cannot be recognized by the control unit.

What Are The Potential Causes Of The Nissan C1105 Code?

- Harness or connector
- Wheel sensor
- ABS actuator and electric unit (control unit)

Reference Sources

[BRAKE CONTROL SYSTEM SERVICE MANUAL for C1105](#) - Page 36.