

NISSAN C16A2: EPS MOTOR ANGLE SENSOR INITIALIZATION

OVERVIEW

Severity	:	High
DIY Difficulty Level	:	Advanced
Repair Cost	:	\$150-\$500
Can I Still Drive?	:	No

What Does The Nissan C16A2 Code Mean?

EPS motor angle sensor initialization is not performed.

What Are The Potential Causes Of The Nissan C16A2 Code?

EPS motor angle sensor initialization not performed

Reference Sources

[STEERING CONTROL SYSTEM SERVICE MANUAL for C16A2](#) - 2008 Altima Hybrid, pages 37-38.