

SUBARU P1152: O2 SENSOR RANGE/PERFORMANCE (LOW) (BANK 1 SENSOR 1)

OVERVIEW

Severity	:	<div><div></div></div> High
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$100-\$300
Can I Still Drive?	:	Yes (Short-term only)

What Does The Subaru P1152 Code Mean?

While driving at a constant speed of 12.4 mph or more: Actual air fuel ratio/Theoretical air fuel ratio < 0.85

What Are The Symptoms Of The Subaru P1152 Code?

Poor drivability.

What Are The Potential Causes Of The Subaru P1152 Code?

- Water in the front oxygen sensor connector or coupling connector
- Wiring harness between ECM and front oxygen sensor needs repair
- Poor contact of front oxygen sensor
- Defective front oxygen sensor

Reference Sources

[2008 Impreza WRX Repair Manual for P1152](#) - Pages 260-261.