

SUBARU P1767: DCCD STEERING ANGLE SENSOR

OVERVIEW

Severity	:	High
DIY Difficulty Level	:	Advanced
Repair Cost	:	\$150-\$500
Can I Still Drive?	:	No

What Does The Subaru P1767 Code Mean?

Open, short or communication failure of the steering angle sensor circuit. A tight corner braking symptom occurs.

What Are The Potential Causes Of The Subaru P1767 Code?

- Open circuit between fuse and DCCD control module, or between fuse and battery
- Faulty steering angle sensor

Reference Sources

[Testing and Inspection for P1767](#) - Pages 23-24.