SUBARU P1769: YAW RATE & LATERAL G SENSOR MALFUNCTION			
	IVIZA	OVERVIEW	
Severity	:	H	High
DIY Difficulty Level	:	Advar	nced
Repair Cost	:	\$550-\$750	
Can I Still Drive?	:	No	

What Does The Subaru P1769 Code Mean?

Yaw rate & lateral G sensor malfunction. A tendency to understeer occurs during high speed cornering.

What Are The Potential Causes Of The Subaru P1769 Code?

- Open circuit between fuse and DCCD control module, or between fuse and battery
- Faulty yaw rate & G sensor

Reference Sources

Testing and Inspection for P1769 - Pages 25-26.