

SUBARU P1840: TRANSMISSION FLUID PRESSURE SENSOR SWITCH A CIRCUIT

OVERVIEW

Severity	:	High
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$170-\$300
Can I Still Drive?	:	No

What Does The Subaru P1840 Code Mean?

Front brake oil pressure switch malfunction. Excessive shift shock felt.

What Are The Potential Causes Of The Subaru P1840 Code?

Open or shorted Fr/B fluid pressure switch or switch malfunction

Reference Sources

- [Technical Service Bulletin 16-86-12 for P1840](#) - 2013MY Legacy, Outback and Tribeca
- [Technical Service Bulletin 16-80-11R for P1840](#) - 2010~13MY Legacy, Outback & Tribeca