

SUBARU P1841: TRANSMISSION FLUID PRESSURE SENSOR SWITCH B CIRCUIT

OVERVIEW

Severity	:	High
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$170-\$300
Can I Still Drive?	:	No

What Does The Subaru P1841 Code Mean?

Forward brake oil pressure switch malfunction. Excessive shift shock felt.

What Are The Potential Causes Of The Subaru P1841 Code?

Open or shorted Fwd/B fluid pressure switch or switch malfunction

Reference Sources

- [Technical Service Bulletin 16-86-12 for P1841](#) - 2013MY Legacy, Outback and Tribeca
- [Technical Service Bulletin 16-80-11R for P1841](#) - 2010~13MY Legacy, Outback & Tribeca