

SUBARU P1842: TRANSMISSION FLUID PRESSURE SENSOR SWITCH C CIRCUIT

OVERVIEW

Severity	:	High
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$170-\$300
Can I Still Drive?	:	No

What Does The Subaru P1842 Code Mean?

Input clutch oil pressure switch malfunction. Excessive shift shock felt.

What Are The Potential Causes Of The Subaru P1842 Code?

Open or shorted I/O fluid pressure switch or switch malfunction

Reference Sources

- [Technical Service Bulletin 16-86-12 for P1842](#) - 2013MY Legacy, Outback and Tribeca
- [Technical Service Bulletin 16-80-11R for P1842](#) - 2010~13MY Legacy, Outback & Tribeca