SUBARU U1222: CAN-HS TCM NO-RECEIVE DATA			
		OVERVIEW	
Severity	:	Medium	
DIY Difficulty Level	:	Intermediate	
Repair Cost	:	\$75-\$200	
Can I Still Drive?	:	Yes	

What Does The Subaru U1222 Code Mean?

Not received error data from TCM.

What Are The Potential Causes Of The Subaru U1222 Code?

- Wiring harness connected to high speed CAN communication line need repair
- Defective TCM
- Defective body integrated unit

Reference Sources

Subaru U1222, DTCDECODE.