

SUBARU U1223: CAN-HS VDC/ABS NO-RECEIVE DATA

OVERVIEW

| | | |
|----------------------|---|------------------------------------|
| Severity | : | <div><div>Medium</div></div> |
| DIY Difficulty Level | : | <div><div>Intermediate</div></div> |
| Repair Cost | : | \$75-\$200 |
| Can I Still Drive? | : | Yes (Short-term only) |

What Does The Subaru U1223 Code Mean?

Not received error data from VDC/ABS CM.

What Are The Potential Causes Of The Subaru U1223 Code?

- Wiring harness connected to high speed CAN communication line need repair.
- Defective VDC/ABS CM.
- Defective body integrated unit.

Reference Sources

[Diagnostic Procedure with Diagnostic Trouble Code for U1223](#) - 2008 Impreza WRX, pages 59-60.