

TOYOTA B1206: P/W MASTER SWITCH COMMUNICATION STOP

OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$30-\$100
Can I Still Drive?	:	Yes (Short-term only)

What Does The Toyota B1206 Code Mean?

No communication between the master switch and main body ECU (cowl side junction block LH) for 10 seconds or more.

What Are The Potential Causes Of The Toyota B1206 Code?

- Master switch
- Main body ECU (cowl side junction block LH)
- Harness or connector

Reference Sources

[Toyota Land Cruiser Tech Doc for B1206](#) - Pages 187-190.