

TOYOTA B1561: XM TUNER DISCONNECTED (COMMAND LINE)

OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$300-\$600
Can I Still Drive?	:	Yes (Short-term only)

What Does The Toyota B1561 Code Mean?

Stereo component tuner assembly is not/was not connected while the power switch is turned on (ACC or IG). (Even if no fault is present, this DTC may be stored depending on the battery condition or hybrid system start voltage.)

What Are The Potential Causes Of The Toyota B1561 Code?

- Stereo component tuner assembly power source circuit
- AVC-LAN circuit between navigation receiver assembly and stereo component tuner assembly
- Navigation receiver assembly
- Stereo component tuner assembly

Reference Sources

[Toyota B1561](#), DTCDECODE.